

Make / Model

Hyundai SANTA FE SPORT ...

Year
Mileage indicated / actual*

2015

177,416 km
Transmission
Drive Type

automatic

AWD

Engine
Fuel Type

4 cyl.

unleaded

Serial number
Stock number

58596A


EQUIPMENTS

Air conditioning, Cruise control, Heated mirrors, Power locks, Power Mirrors, Power driver seat, Power sliding doors, Power steering, Power windows, Remote Entry, Adjustable steering wheel, Heated steering, Heated back seats, ABS Brakes, Driver airbag, Passenger airbag, Rear defrost, Lateral airbags, Stability control, Traction control, Intermittent wipers, Rain sensor wipers, Sunroof, Rear spoiler, Two-toned paint, AM/FM stereo, Bluetooth, CD player, MP3 Player, Satellite radio, Bucket seats, Stow'n Go, Tachometer, Reverse camera, Variable speed intermittent wipers, Child safety locks, Climate control, Integrated turn signal mirrors, Driver vanity mirror, Passenger vanity mirror, Driver illuminated vanity mirror, Mirror memory, Pass-Through rear seat, Leather seats, Split bench seat, Power passenger seat, Tire pressure monitoring system, Panoramic roof, Rear head air bag, Front floor mats, Anti-theft system, Brake assist, Auxiliary audio input, Universal garage door opener, Keyless en

SALE PRICE

\$10,299

Plus tax.

Owner and prior usage

The following business or public organization leased or owned this vehicle long term :

This vehicle was previously used for :

The dealer will supply upon request the name and phone number of the last owner.

Category

Subject to admissibility of the transfer and the conditions and exceptions stated in the warranty contract, this vehicle comprises of a:

Legal warranty : D - None (LPC 37,38)

As per articles 159 and 160 of the consumer protection act, (1978,c9) this automobile is part of the category below and has a valid warranty for the duration of the term or mileage, whichever is attained first, indicated below:

A ☐ 6 months or 10 000 km B ☐ 3 months or 5 000 km C ☐ 1 month or 1 700 km

D ☐ Good working (subject to 37, 38 L.P.C.) E ☐ No warranty

Repairs done and mechanical verification certificate
Comments

The following repairs have been done on this vehicle since the dealer's possession.

If necessary, the dealer will submit a mechanical verification certificate in accordance with the Highway Safety Code.

Optional repairs

The following defects have been noted on this vehicle and can be repaired at the cost mentioned below :

This evaluation is valid until delivery of the vehicle. I attest to having received a copy of the window sticker.

Date : _____ Signature : _____

autoExpert.ca

Sticker # : 8750331