Groupe Autoforce Occasion AUTOFORCE 2100, boul. du Traversier OCCASION 1 844 689-5838 Pincourt J7V 0K8 Make / Model Mazda CX5 GX CARPLAY CAM ... Mileage indicated / actual* Year 2021 70.030 km Transmission **Drive Type** FWD automatic Engine **Fuel Type** 4 cyl. unleaded Serial number Stock number 57910A **EQUIPMENTS** SALE PRICE Air conditioning, Cruise control, Heated mirrors, Power Mirrors. Power steering, Power windows, Adjustable steering wheel, Driver airbag, Passenger airbag, Rear defrost, Stability control, Traction 23,477 control, Intermittent wipers, Rain sensor wipers, Rear spoiler, Twotoned paint, Bucket seats, Reverse camera, Variable speed intermittent wipers, Child safety locks, Integrated turn signal mirrors, Driver vanity mirror, Passenger vanity mirror, Pass-Through rear seat, Rear head air bag, Front floor mats, Brake assist, Auxiliary audio input, Keyless entry, Auto-on headlights, Keyless start, Plus tax. Remote trunk release, Audio steering controls Owner and prior usage The following business or public organization leased or owned this This vehicle was previously used for : vehicle long term : The dealer will supply upon request the name and phone number of the last owner Category As per articles 159 and 160 of the consumer protection act, (1978,c9) this automobile is part of the category below and has a valid warranty for the duration of the term or mileage, whichever is attained first, indicated below: Subject to admissibility of the transfer and the conditions and exceptions stated in the warranty contract, this vehicle comprises of a: Legal warranty : C - 1 month - 1700 KM A 6 months or 10 000 km 3 months or 5 000 km 1 month or 1 700 km вΓ С Good working (subject to 37, 38 L.P.C.) E No warranty D Comments Repairs done and mechanical verification certificate The following repairs have been done on this vehicle since the dealer's possession. If necessary, the dealer will submit a mechanical verification certificate in accordance with the Highway Safety Code. **Optional repairs** The following defects have been noted on this vehicle and can be repaired at the cost mentioned below : This evaluation is valid until delivery of the vehicle. I attest to having received a copy of the window sticker. auto Expert... Date : Signature :

Sticker # : 8585371